


UO-3500 MOTOR ASSEMBLY AND PARTS LIST



The Part Numbers with () are included in the Ass'y parts written above them.

No.	Part No.	Part Name	Q'ty	Price
1	TQ07142	Gear Case	1	
2	TQ01856	Pan Head Screw 5 X 50	4	
3	TQ07144	Spindle	1	
4	TP16497	Key 5 X 5 X 7	1	
5	TP01632	Ball Bearing 6203Z	1	
6	TQ00858	Bearing Supporter	1	
7	TP11492	Pan Head Screw 5 X 10	4	
8	TQ00860	Collar	1	
9	TQ07145	Helical Gear B	1	
10	CP04989	External Retaining Ring C15	1	
11	TP06626	Ball Bearing 6200	1	
12	TP00468	Ball Bearing 608ZZ	1	
13	TQ07146	Pinion Gear	1	
14	TQ03980	Key 3 X 3 X 5	1	
15	TQ07147	Helical Gear A	1	

No.	Part No.	Part Name	Q'ty	Price
17	TB05499	Bearing Bracket Ass'y	1 set	
18	TQ01436	Fan Guide	1	
19	TQ07149	Ball Bearing 6200DU	4	
20	TB05498	Armature Ass'y (115V)	1 set	
21	TB01012	Stator Ass'y (115V)	1 set	
22	TQ00870	Motor Housing	1	
23	TQ00869	Insulation Washer	2	
24	TQ00868	Brush Holder	1	
25	TB00598	Carbon Brush Ass'y	1 set	
26	TQ00867	Brush Cap	1	
27	TP13362	Cord Holder	1	
28	LP30251	Pan Head Screw 4 X 16	1	
29	TP16481	Condenser	1	
30	TP13363	Strain Reliever	1	
31	TQ07150	Connecting Cable	1	